

Product Safety Recall



Clipsal

Socket Outlet 10mA RCD and Service Panel 10mA RCD
2025RC10-XX, 2031RC10-XX, 2031VRC10-XX, C2025RC10-XX, ML2025RC10C-BG,
ML2025RC10-XX, ML2031RC10-XX, ML2031VRC10-XX
1st July 2017 and 15th October 2020

Defect: *May not trip below the correct current limit.*

Hazard: *If a faulty electrical appliance is energized downstream of a product in scope of this recall the product will not disconnect the supply of electricity at the required limit of 10mA.*

What to do: *All products purchased between 1st July 2017 and 15th October 2020 are potentially affected and need to be replaced.*

Contact details:

phone: 0800 652 999

email: customercare.nz@se.com

New Zealand Importer/Distributor

Schneider Electric NZ
2/4 Hazeldean Rd, Addington,
Christchurch,
New Zealand
0800 652 999

See www.recalls.govt.nz for
other New Zealand consumer product recalls